

Thousands... if you do not drop it, overheat it, put too much pressure through it over 4,000 psi, subject it to *pressure shock* or inject anything on the column that is not part of the HSQ Kit™.

Click [HERE](#) for HSQ Kit ordering information and pictures.

Printed from the Chrom Resource Center

Copyright 2024, All Rights Apply

MicroSolv Technology Corporation

9158 Industrial Blvd. NE, Leland, NC 28451

tel. (732) 380-8900, fax (910) 769-9435

Email: customers@mtc-usa.com

Website: www.mtc-usa.com