



Why do the PEEK columns not have wrench flats on them - FAQ

Machining the column body tubes to create wrenching flats will weaken the PEEK tubes and reduce the pressure rating by approximately 100 bar.

Therefore for maximum column efficiency and pressure ratings, we do not include wrenching flats on our All-PEEK™ HPLC column hardware.

Printed from the Chrom Resource Center

MicroSolv Technology Corporation

9158 Industrial Blvd. NE, Leland, NC 28451

tel. (732) 380-8900, fax (910) 769-9435

Email: customers@mtc-usa.com

Website: www.mtc-usa.com

Date: 07-22-2024