


What is the purpose of the two unthreaded holes in some of the low pressure unions - FAQ

The unthreaded holes were once introduced to place Tees & Crosses safely on or in an instrument or a lattice.



Printed from the Chrom Resource Center

Copyright 2024, All Rights Apply

MicroSolv Technology Corporation

9158 Industrial Blvd. NE, Leland, NC 28451

tel. (732) 380-8900, fax (910) 769-9435

Email: customers@mtc-usa.com

Website: www.mtc-usa.com