


What is the purpose of the two unthreaded holes in some of the low pressure unions - FAQ

The unthreaded holes were once introduced to place Tees & Crosses safely on or in an instrument or a lattice.



Printed from the Chrom Resource Center Copyright 2025, All Rights Apply **MicroSolv Technology Corporation** 9158 Industrial Blvd. NE, Leland, NC 28451 Tel: (732) 380-8900 Fax: (910) 769-9435 Email: customers@mtc-usa.com Website: www.mtc-usa.com