

Unions can normally withstand about 600 bar, it will be the nut and ferrule connection and the tubing which will be the weakest link and restricting part. That is where a leak could occur before the union fails.

Printed from the Chrom Resource Center

Copyright 2024, All Rights Apply

MicroSolv Technology Corporation

9158 Industrial Blvd. NE, Leland, NC 28451

tel. (732) 380-8900, fax (910) 769-9435

Email: customers@mtc-usa.com

Website: www.mtc-usa.com